

TrailerWIN fix 2017-08

Valid for: TrailerWIN versions from 2016-03 until 2017-05 manufactured between 23.2.2016 and 04.08.2017.

Description: Wrong wheelbase on MB Sprinter 906 Short Cab 3,5t WB 3665 and Wrong rear overhang on models MB Sprinter 906 Crew cab 5,0t WB 3665 and WB 4325


Solution: Installing this update package will correct the data into TrailerWIN. Note that this package is only for program discs manufactured between above mentioned dates.

Steps:


On our homepage: www.trailerwin.com select "Support" and "Fixes" or click on this link:
<https://www.trailerwin.com/userfiles/images/Fixes/2017-08%20Mercedes-Sprinter-906.zip>

or write the address directly in the address-field of Your web-browser.


Note: Following instructions and pictures are examples.

<p>When pop-up download appears: Choose Save</p>	
---	--


Choose Open






When file opens in zip-program
Choose Extract



When asked for destination, choose the directory
where TrailerWIN is installed. Normally C:\TrailerW.
Choose C:\TrailerW



<p>When warned about folder already exists, Choose Merge</p>	
<p>When warned about same files already exists: Check "Don't ask me again" and click Replace.</p>	
<p>Files extracted successfully</p>	

Re-start TrailerWIN and the data will be correct next time you select above mentioned models.

If problem persists: Please contact Trailer Consultation with example of outprint and original TrailerWIN file attached.

E-mail: info@trailerwin.com