

TrailerWIN fix 2025-02




Valid for: TrailerWIN versions 2024-02 to 2025-01 manufactured before 4.2.2025.

Description: Wrong information for outreach on Hiab Ix 158 HiDuo D-5


Solution: Installing correction package in this fix

Steps:


Note: Following instructions and pictures are examples.

<p>Download the package from www.trailerwin.com (ZIP-file): Click on the ZIP-icon (correction package) and download it to your computer</p>	
<p>Open the zip-file</p>	
<p>When file opens in zip-program Choose Extract</p>	


When asked for destination, choose the directory where TrailerWIN is installed. Normally C:\TrailerW.
Choose C:\TrailerW




When warned about folder already exists,
Choose Merge



When warned about same files already exists:
Check "Don't ask me again" and click Replace.





If you have an earlier version of TrailerWIN and need this crane range you need to order complete update.

If problem persists: [Please contact Trailer Consultation](#)

E-mail: info@trailerwin.com