

TrailerWIN fix 2019-09

Valid for: TrailerWIN version 2018-01 until version 2019-05 manufactured before 05.09.2019.

Description: Selecting tailgate lifter results in data&drawing from wrong lifter model in TrailerWIN



Solution: Installing this update package will correct the error with wrong selection and the model selection will give correct tailgate lifter data and drawing




Steps:



Click on this link: <https://www.trailerwin.com/userfiles/images/Fixes/2019-09 Bär Cargolift.zip>

or write the address in the address-field of Your web-browser. Note the new link to fixes !

Note: Following instructions and pictures are examples.

<p>Download the package from www.trailerwin.com (ZIP-file): Click on the ZIP-icon (correction package) and download it to your computer</p>	
<p>Open the zip-file</p>	

<p>When file opens in zip-program Choose Extract</p>	
<p>When asked for destination, choose the directory where TrailerWIN is installed. Normally C:\TrailerW. Choose C:\TrailerW</p>	
<p>When warned about folder already exists, Choose Merge</p>	

<p>When warned about same files already exists: Check "Don't ask me again" and click Replace.</p>	
<p>Files extracted successfully</p>	

Re-select HMF crane groups and you will find the missing models. If you have an earlier version of TrW you need to order complete update !

If problem persists: [Please contact Trailer Consultation with example of outprint and original TrailerWIN file attached.](#)

E-mail: info@trailerwin.com