

TrailerWIN fix 2024-05

Valid for: TrailerWIN version 2024-01 – 2024-5 manufactured before 14.5.2024.




Description: Due to error in our files the axle layout for certain DAF XB models was wrong.


Solution: Installing the fix will correct the data for DAF XB models that doesn't show correct axle layout corresponding to the model designation

Steps:

Note: Following instructions and pictures are examples.

<p>Download the package from www.trailerwin.com (ZIP-file): Click on the ZIP-icon (correction package) and download it to your computer</p>	
<p>Open the zip-file</p>	
<p>When file opens in zip-program Choose Extract</p>	

<p>When asked for destination, choose the directory where TrailerWIN is installed. Normally C:\TrailerW. Choose C:\TrailerW</p>	
<p>When warned about folder already exists, Choose Merge</p>	
<p>When warned about same files already exists: Check "Don't ask me again" and click Replace.</p>	



If you have an earlier version of TrailerWIN and need this crane range you need to order complete update.

If problem persists: [Please contact Trailer Consultation](#)

E-mail: info@trailerwin.com