

## TrailerWIN fix 2024-09




**Valid for:** TrailerWIN version 2023-01 – 2024-5 manufactured before 26.9.2024.

**Description:** Missing drawing for Palfinger PK 16002 HP 2(A)


**Solution:** Installing missing drawing into TrailerWIN

### Steps:


Note: Following instructions and pictures are examples.

<p>Download the package from <a href="http://www.trailerwin.com">www.trailerwin.com</a> (ZIP-file):  <b>Click on the ZIP-icon (correction package) and download it to your computer</b></p>	
<p><b>Open the zip-file</b></p>	
<p>When file opens in zip-program  <b>Choose Extract</b></p>	


When asked for destination, choose the directory where TrailerWIN is installed. Normally C:\TrailerW.  
**Choose C:\TrailerW**




When warned about folder already exists,  
**Choose Merge**



When warned about same files already exists:  
**Check "Don't ask me again" and click Replace.**





If you have an earlier version of TrailerWIN and need this crane range you need to order complete update.

If problem persists: [Please contact Trailer Consultation](#)

E-mail: [info@trailerwin.com](mailto:info@trailerwin.com)