

TrailerWIN fix 2018-01

Valid for: TrailerWIN versions 2017-07 manufactured between 11.9.2017 and 19.01.2018.

Description: This is an updated cumulative correction package including all corrections on launched cranes in version 2017-07. If you have installed the previous package, please update again with this updated package that also includes corrections for COG on X-Hipro 408 model ! Corrected stabilizer leg width for 6.8m leg from 5.8->6.8m for X-CLX398, X-Hipro408, X-Hipro418. Corrected capacity (2060kg) for X-Hipro858E10. Corrected COG for X-Hipro 408.

Solution: Installing this update package will correct the drawing in TrailerWIN. Note that this package is only for program discs manufactured between above mentioned dates.


Steps:

On our homepage: www.trailerwin.com select "Support" and "Fixes" or click on this link:


https://www.trailerwin.com/userfiles/images/Fixes/2018-01_HIAB.zip

or write the address directly in the address-field of Your web-browser.


Note: Following instructions and pictures are examples.

<p>When pop-up download appears: Choose Save</p>	 <table border="1"><thead><tr><th>Date</th><th>Problem</th><th>Suitable for versions</th><th>Installation guide</th><th>Correction package</th></tr></thead><tbody><tr><td>07.08.2017</td><td>Wrong crane drawing on 2 types cranes HT130E and HT142 E and 2 Forest cranes T130D A and T142 A.</td><td>TrailerWIN versions 2016-08 -> 2017-00 until 4.8.2017</td><td></td><td></td></tr><tr><td>07.08.2017</td><td>Wrong data on crane knee ends Sprinter 500 (R0049)</td><td>TrailerWIN versions 2016-03 -> 2017-00 until 4.8.2017</td><td></td><td></td></tr><tr><td>19.04.2017</td><td>Problems updating due to error on established part</td><td>All versions on computers without other version of TrailerWin's installed</td><td></td><td></td></tr><tr><td></td><td>Wrong capacity data for lift 610, 710, 810, 910-series cranes (includes carrier correction)</td><td>TrailerWIN 2017-03</td><td></td><td></td></tr></tbody></table>	Date	Problem	Suitable for versions	Installation guide	Correction package	07.08.2017	Wrong crane drawing on 2 types cranes HT130E and HT142 E and 2 Forest cranes T130D A and T142 A.	TrailerWIN versions 2016-08 -> 2017-00 until 4.8.2017			07.08.2017	Wrong data on crane knee ends Sprinter 500 (R0049)	TrailerWIN versions 2016-03 -> 2017-00 until 4.8.2017			19.04.2017	Problems updating due to error on established part	All versions on computers without other version of TrailerWin's installed				Wrong capacity data for lift 610, 710, 810, 910-series cranes (includes carrier correction)	TrailerWIN 2017-03		
Date	Problem	Suitable for versions	Installation guide	Correction package																						
07.08.2017	Wrong crane drawing on 2 types cranes HT130E and HT142 E and 2 Forest cranes T130D A and T142 A.	TrailerWIN versions 2016-08 -> 2017-00 until 4.8.2017																								
07.08.2017	Wrong data on crane knee ends Sprinter 500 (R0049)	TrailerWIN versions 2016-03 -> 2017-00 until 4.8.2017																								
19.04.2017	Problems updating due to error on established part	All versions on computers without other version of TrailerWin's installed																								
	Wrong capacity data for lift 610, 710, 810, 910-series cranes (includes carrier correction)	TrailerWIN 2017-03																								


Choose Open






When file opens in zip-program
Choose Extract



When asked for destination, choose the directory where TrailerWIN is installed. Normally C:\TrailerW.
Choose C:\TrailerW



<p>When warned about folder already exists, Choose Merge</p>	
<p>When warned about same files already exists: Check "Don't ask me again" and click Replace.</p>	
<p>Files extracted successfully</p>	

Re-start TrailerWIN and re-select the HIAB cranes listed if one of the above mentioned in the calculation and verify that the data is correct.

If problem persists: Please contact Trailer Consultation with example of outprint and original TrailerWIN file attached.

E-mail: info@trailerwin.com