

TrailerWIN fix 2019-02

Valid for: TrailerWIN version 2018-08 until version 2019-01 manufactured before 24.01.2019.

Description: Missing models HMF 1610K1, 1610K12, 1620K1 and 1620K2-series cranes in update 2018-08


Solution: Installing this update package will add the data for missing models into TrailerWIN. Note that this package is only for program discs manufactured between above mentioned dates.




Steps:

Click on this link: <http://www.trailerwin.com/userfiles/images/Fixes/2019-02 HMF 1610-1620.zip>

or write the address in the address-field of Your web-browser. Note the new link to fixes !

Note: Following instructions and pictures are examples.

<p>When pop-up download appears: Choose Save</p>	 <p>The screenshot shows a web browser window displaying the TrailerWIN software interface. The interface includes a menu bar, a toolbar, and a main workspace with a technical drawing of a truck chassis. A download pop-up window is visible at the bottom of the browser, asking to save a file named '2012entlo.zip' (344 KB) from 'www.trailerwin.com?'. The pop-up has 'Open', 'Save', and 'Cancel' buttons.</p>
---	--

<p>When warned about folder already exists, Choose Merge</p>	
<p>When warned about same files already exists: Check "Don't ask me again" and click Replace.</p>	
<p>Files extracted successfully</p>	

Re-select HMF crane groups and you will find the missing models. If you have an earlier version of TrW you need to order complete update !

If problem persists: Please contact Trailer Consultation with example of outprint and original TrailerWIN file attached.

E-mail: info@trailerwin.com