

## TrailerWIN fix 2024-11




**Valid for:** TrailerWIN versions up to 2024-08 manufactured before 12.11.2024.




**Description:** Wrong data for CoG of boom at max outreach in CraneWIN.


**Solution:** Correct by installing zip-file in link.Corrected data in updates manufactured after 12.11.2024

### Steps:

Note: Following instructions and pictures are examples.

<p>Download the package from <a href="http://www.trailerwin.com">www.trailerwin.com</a> (ZIP-file):  <b>Click on the ZIP-icon (correction package) and download it to your computer</b></p>	
<p><b>Open the zip-file</b></p>	
<p>When file opens in zip-program  <b>Choose Extract</b></p>	

<p>When asked for destination, choose the directory where TrailerWIN is installed. Normally C:\TrailerW. <b>Choose C:\TrailerW</b></p>	
<p>When warned about folder already exists, <b>Choose Merge</b></p>	
<p>When warned about same files already exists: <b>Check "Don't ask me again" and click Replace.</b></p>	



If you have an earlier version of TrailerWIN and need this crane range you need to order complete update.

If problem persists: [Please contact Trailer Consultation](#)

E-mail: [info@trailerwin.com](mailto:info@trailerwin.com)